

Location Information			System-Owned Portion				Customer-Owned Portion				Additional Information	
Unique Service Line ID	Location Identifier	Street Address	System-Owned Portion Service Line Material Classification	Service Line Size	If "Yes" Service Line Material Was Field Verified: Describe the Field Verification Method	Enter the Date of Field Verification	Customer-Owned Portion Service Line Material Classification	Service Line Size	If "Yes" Service Line Material Was Field Verified: Describe the Field Verification Method	Enter the Date of Field Verification	Entire Service Line Material Classification	Building Type Connected to Service Line
A Unique ID is recommended for each service line.	A Unique ID is recommended for each service line.	Water systems must track addresses of all service lines in their internal inventory. For the publicly accessible version, location identifiers are required for lead and galvanized required.	Dropdown list includes recommended subclassifications. If "Non-Lead, Other", describe in Notes field.	Diameter in inches	Select option from drop down list. If "Other," describe in the Notes field.	Enter approximate date of field verification or date that the record was	Dropdown list includes recommended subclassifications. If non-lead other, describe in	Diameter in inches	Select option from drop down list. If "Other," describe in the Notes field	Enter approximate date of field verification or date that the record was	Dropdown list includes four required service line classifications of Lead, Non-lead, Galvanized Requiring Replacement, or Unknown.	Note: This information may be helpful for identifying lead tap monitoring locations.
KC#	FID	LOCATION		MODEL	Visual inspection at the meter pit	UPD By					Non-Lead	
1	310	3090 SOUTH 1100 W	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/17/2024	Non-Lead - Copper	.75 inch M25	Customer self-identification	09/17/2024	Non-Lead	Single Family Residence
2	312	3220 SOUTH 1100 W	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	7/31/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/17/2024	Non-Lead	Single Family Residence
3	99	385 WEST GREGSON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	7/31/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	07/31/2024	Non-Lead	Single Family Residence
4	75	3125 SOUTH ELDREDGE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	7/31/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	7/31/2024	Non-Lead	Single Family Residence
5	76	3260 SOUTH ELDREDGE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	7/31/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	7/31/2024	Non-Lead	Building
6	190	3165 SOUTH 300 W	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/1/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/01/2024	Non-Lead	Building
7	309	3112 SOUTH 300 W	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/26/2024	Non-Lead	Building
8	307	300 W 3000 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/1/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/01/2024	Non-Lead	Building
9	306	2900 S 300 W	Galvanized	2.00 inch M170	Visual inspection at the meter pit	8/1/2024	Galvanized	2.00 inch M170	Visual inspection at the meter pit	08/01/2024	Non-Lead	Building
10	305	2895 S 300 W	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	08/26/2024	Non-Lead	Building
11	109	400 WEST LAWNDALE DR	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	8/1/2024	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	08/01/2024	Non-Lead	Building
12	303	2635 S 300 W	Non-Lead - Copper	1.5 inch M120	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	1.5 inch M120	Visual inspection at the meter pit	08/26/2024	Non-Lead	Building
13	145	175 W OAKLAND AVE	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	8/1/2024	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	08/01/2024	Non-Lead	Single Family Residence
14	144	119 W OAKLAND AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/1/2024	Unknown - Unlikely Lead	.75 inch M25	Visual inspection at the meter pit	08/01/2024	Non-Lead	Building
15	250	2455 S WEST TEMPLE	Galvanized	.75 inch M25	Visual inspection at the meter pit	8/1/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/01/2024	Non-Lead	Building
16	189	133 W STRATFORD AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/1/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/01/2024	Non-Lead	Building
17	73	145 W CRYSTAL AVE	Non-Lead - Copper	2.00 inch M170	Visual inspection at the meter pit	8/1/2024	Unknown - Material Unknown	2.00 inch M170	Visual inspection at the meter pit	08/01/2024	Non-Lead	Building
18	133	155 W MALVERN AVE	Unknown - Material Unknown	1.00 inch M70	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	08/26/2024	Non-Lead	Building
19	352	154 W 2700 S	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	08/26/2024	Non-Lead	Building
20	351	125 W 2700 S	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/29/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/29/2024	Non-Lead	Building
21	355	150 W 2950 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/2/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/02/2024	Non-Lead	Building

22	354	135 W 2950 S	Unknown - Material Unknown	Recordall 5/8 x 3/4	Visual inspection at the meter pit	8/2/2024	Non-Lead - Plastic	Recordall 5/8	Visual inspection at the meter pit	08/02/2024	Non-Lead	
23	357	158 W 3030 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/2/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/02/2024	Non-Lead	
24	356	113 W 3030 S	Unknown - Material Unknown	1 INCH M70	Visual inspection at the meter pit	8/2/2024	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	08/02/2024	Non-Lead	
25	97	152 W GREGSON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	08/26/2024	Non-Lead	Single Family Residence
26	98	205 W GREGSON AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	08/26/2024	Non-Lead	Single Family Residence
27	302	149 W GREGSON AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/26/2024	Non-Lead	Single Family Residence
28	308	3094 SOUTH WEST TEMPLE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	08/26/2024	Non-Lead	Single Family Residence
29	16	190 W ANGELO AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/2/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/02/2024	Non-Lead	
30	363	121 W ANGELO AVENUE	Non-Lead - Plastic	1.00 inch M70	Visual inspection at the meter pit	8/2/2024	Unknown - Material Unknown	1.00 inch M70	Visual inspection at the meter pit	08/02/2024	Non-Lead	
31	254	3166 SOUTH WEST TEMPLE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/2/2024	Unknown - Material Unknown	.75 INCH M25	Visual inspection at the meter pit	08/02/2024	Non-Lead	Single Family Residence
32	232	115 W WALTON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/2/2024	Unknown - Material Unknown	.75 inch M25	Visual inspection at the meter pit	08/02/2024	Non-Lead	Single Family Residence
33	256	3205 SOUTH WEST TEMPLE	Non-Lead - Copper	.75 inch M26	Visual inspection at the meter pit	8/5/2024	Non-Lead - Copper	1 INCH M25	Visual inspection at the meter pit	08/05/2024	Non-Lead	Single Family Residence
34	150	3264 SOUTH RICHARDS ST	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/5/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/05/2024	Non-Lead	Single Family Residence
35	149	3263 SOUTH RICHARDS ST	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/5/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	08/05/2024	Non-Lead	Single Family Residence
36	361	3193 SOUTH RICHARDS ST	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	8/5/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	08/05/2024	Non-Lead	Single Family Residence
37	96	19 W GREGSON AVE	Non-Lead - Copper	2 inch M170	Visual inspection at the meter pit	8/5/2024	Non-Lead - Plastic	2 inch M170	Visual inspection at the meter pit	08/05/2024	Non-Lead	Single Family Residence
38	353	69 WEST 2950 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/06/2024	Non-Lead	Building
39	291	30 W 2950 S	Galvanized	.75 INCH M25	Visual inspection at the meter pit	8/5/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	08/05/2024	Non-Lead	Building
40	125	35 WEST LOUISE AVE	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	08/26/2024	Non-Lead	Building
41	126	80 WEST LOUISE AVE	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/29/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	08/29/2024	Non-Lead	Building
42	198	74 WEST SUNSET AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/06/2024	Non-Lead	Single Family Residence
43	197	37 WEST SUNSET AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residence
44	163	63 WEST RUSSETT AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/06/2024	Non-Lead	Single Family Residence
45	164	78 WEST RUSSETT AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/06/2024	Non-Lead	Single Family Residence
46	162	40 WEST RUSSETT AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/6/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	08/06/2024	Non-Lead	Single Family Residence
47	167	92 WEST SHELLEY AVE	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	08/06/2024	Non-Lead	Single Family Residence

48	350	89 WEST 2700 S	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/28/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/28/2024	Non-Lead	Single Family Residence
49	349	48 WEST 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/26/2024	Non-Lead	Single Family Residence
50	347	36 WEST 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/26/2024	Non-Lead	Single Family Residence
51	132	96 WEST MALVERN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/7/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
52	130	26 W MALVERN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Single Family Residence
53	72	73 WEST CRYSTAL AVE	Galvanized	.75 inch M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
54	71	12 W CRYSTAL AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Single Family Residence
55	188	57 WEST STRATFORD AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Single Family Residence
56	143	55 WEST OAKLAND AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Multiple Family Residence
57	156	41 WEST ROBERT AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Single Family Residence
58	155	11 W ROBERT AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/6/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Single Family Residence
59	293	48 EAST 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Building
60	168	35 EAST SOUTHGATE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/6/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Single Family Residence
61	169	90 EAST SOUTHGATE AVE	Unknown - Material Unknown	.75 INCH M25	Visual inspection at the meter pit	8/6/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	8/06/2024	Non-Lead	Single Family Residence
62	59	73 EAST CLAYBOURNE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
63	276	20 E CLAYBOURNE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
64	58	46 EAST CLAYBOURNE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Building
65	191	25 E SUNSET AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
66	183	2810 S STATE ST	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Building
67	121	74 EAST LOUISE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
68	120	16 E LOUISE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
69	64	4 EAST CORDELIA AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
70	67	2870 S STATE ST	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Building
71	8	35 EAST WHITE PL	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	09/11/2024	Non-Lead	Building
72	362	56 E White Pl	Non-Lead - Copper		Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper		Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residence
73	86	51 EAST GREGSON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residence

74	184	3080 SOUTH STATE ST	Unknown - Material Unknown	.75 INCH M70	Visual inspection at the meter pit	8/7/2024	Unknown - Material Unknown	.75 INCH M70	Visual inspection at the meter pit	8/07/2024	Non-Lead	Building
75	14	21 E ANGELO AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
76	15	50 EAST ANGELO AVE	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/7/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/07/2024	Non-Lead	Single Family Residence
77	186	3212 SOUTH STATE ST	Non-Lead - Copper	.75 INCH M70	Visual inspection at the meter pit	8/7/2024	Non-Lead - Copper	.75 INCH M70	Visual inspection at the meter pit	8/07/2024	Non-Lead	Building
78	0	136 E 3185 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead	Multiple Family Residence
79	1	155 E 3185 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead	Single Family Residence
80	2	169 E 3185 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead	Single Family Residence
81	304	3034 S 200 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/14/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	8/14/2024	Non-Lead	Single Family Residence
82	87	148 E GREGSON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead	Single Family Residence
83	77	116 E GARDEN AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/14/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	8/14/2024	Non-Lead	Single Family Residence
84	78	155 E GARDEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/14/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/14/2024	Non-Lead	Single Family Residence
85	192	130 E SUNSET AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/14/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/14/2024	Non-Lead	Single Family Residence
86	193	160 E SUNSET AVE	Unknown - Material Unknown	.75 INCH M25	Visual inspection at the meter pit	8/14/2024	Unknown - Material Unknown	.75 INCH M25	Visual inspection at the meter pit	8/14/2024	Non-Lead	
87	194	190 E SUNSET AVE	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	8/14/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/14/2024	Non-Lead	Single Family Residence
88	337	2792 S 200 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/15/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/15/2024	Non-Lead	Multiple Family Residence
89	277	170 E CLAYBOURNE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/15/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/15/2024	Non-Lead	Single Family Residence
90	181	2763 S STATE ST	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/15/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/15/2024	Non-Lead	Building
91	170	158 E SOUTHGATE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/11/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residence
92	171	190 E SOUTHGATE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/15/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/15/2024	Non-Lead	Single Family Residence
93	332	117 E 2700 S	Non-Lead - Copper	1.00 inch M25	Visual inspection at the meter pit	8/29/2024	Unknown - Material Unknown	1.00 inch M25	Visual inspection at the meter pit	08/29/2024	Non-Lead	Building
94	333	152 E 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/29/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/29/2024	Non-Lead	Single Family Residence
95	334	159 E 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/26/2024	Non-Lead	Single Family Residence
96	335	193 E 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
97	113	160 E LESLIE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/15/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/15/2024	Non-Lead	Single Family Residence
98	112	155 E LESLIE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/15/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	08/15/2024	Non-Lead	Single Family Residence
99	110	117 E LESLIE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/15/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/15/2024	Non-Lead	Single Family Residence



126	114	212 E LESLIE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/19/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/19/2024	Non-Lead	Single Family Residence
127	331	2595 S 200 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/19/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/19/2024	Non-Lead	Single Family Residence
128	336	210 E 2700 S	Non-Lead - Copper	.75 INCH M 25	Visual inspection at the meter pit	8/28/2024	Non-Lead - Copper	.75 INCH M 25	Visual inspection at the meter pit	8/28/2024	Non-Lead	Single Family Residence
129	338	260 E 2700 S	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/26/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/26/2024	Non-Lead	Single Family Residence
130	339	280 EAST 2700 S	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/29/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/29/2024	Non-Lead	Single Family Residence
131	129	2720 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Non-Lead	Single Family Residence
132	131	2734 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Unknown - Material Unknown	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Non-Lead	Single Family Residence
133	173	235 E SOUTHGATE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/19/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/19/2024	Non-Lead	Single Family Residence
134	172	203 E SOUTHGATE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/19/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	8/19/2024	Non-Lead	Single Family Residence
135	60	211 E CLAYBOURNE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead	Single Family Residence
136	61	245 E CLAYBOURNE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead	Single Family Residence
137	62	279 E CLAYBOURNE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residence
138	135	2754 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
139	148	2852 S 300 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
140	124	252 E LOUISE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
141	123	211 E LOUISE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
142	348	2880 S 200 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
143	65	222 E CORDELIA AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
144	66	269 E CORDELIA AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
145	69	294 E CORDELIA AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
146	82	292 E GARDEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
147	80	258 EGARDEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/20/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/20/2024	Non-Lead	Single Family Residence
148	79	213 E GARDEN AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residence
149	358	2945 S 200 E	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residence
150	233	243 E WELBY AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residence
151	234	275 E WELBY AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence

152	174	2950 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/21/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residence
153	178	2974 S 300 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residence
154	91	296 E GREGSON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence
155	90	255 E GREGSON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence
156	89	225 E GREGSON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence
157	88	205 E GREGSON AVE	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Multiple Family Residence
158	278	3042 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence
159	17	3095 SOUTH 200 E	Non-Lead - Copper	1.00 INCH M70	Visual inspection at the meter pit	8/22/2024	Non-Lead - Plastic	1.00 INCH M70	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence
160	180	3112 SOUTH 300 E	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence
161	182	3116 SOUTH 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence
162	187	3150 SOUTH 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residence
163	294	3153 SOUTH 200 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
164	68	256 E CRESTONE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
165	38	3195 SOUTH 200 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
166	207	3200 SOUTH 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
167	209	3245 SOUTH 300 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Building
168	299	3234 SOUTH 500 E	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	8/30/2024	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	08/30/2024	Non-Lead	Single Family Residence
169	264	444 EAST WOODLAND AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
170	263	419 EAST WOODLAND AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
171	259	3185 SOUTH 400 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
172	296	3196 SOUTH 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Single Family Residence
173	175	445 EAST STANLEY AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
174	176	452 EAST STANLEY AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residence
175	177	487 EAST STANLEY AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/28/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residence
176	295	3154 SOUTH 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
177	108	475 EAST LAMBOURNE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence

178	107	428 EAST LAMBOURNE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
179	255	3180 SOUTH 400 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
180	106	370 EAST LAMBOURNE AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
181	185	3171 S 300 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/17/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/17/2024	Non-Lead	Single Family Residence
182	134	334 EAST MANSFIELD AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/13/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/13/2024	Non-Lead	Single Family Residence
183	251	3121 SOUTH 400 E	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
184	330	451 EAST GRANITE AVE	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
185	85	459 EAST GRANITE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/28/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residence
186	249	3087 SOUTH 400 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/28/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residence
187	292	3064 SOUTH 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/28/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Multiple Family Residence
188	252	356 EAST PARK CREEKE LN	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
189	92	326 EAST GREGSON AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/28/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residence
190	93	363 EAST GREGSON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/28/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residence
191	13	2995 S ADAMS CIR	Unknown - Material Unknown	.75 inch M25	Visual inspection at the meter pit	9/2/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/02/2024	Non-Lead	Single Family Residence
192	39	2982 S BLAIR ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/30/2024	Non-Lead	Single Family Residence
193	289	2994 S 500 E	Non-Lead - Copper		Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper		Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
194	288	2956 S 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
195	239	445 EAST WELBY AVE	Non-Lead - Copper	1 inch M70	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	1 inch M70	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
196	238	410 EAST WELBY AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residence
197	237	375 EAST WELBY AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residence
198	236	346 EAST WELBY AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/12/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/12/2024	Non-Lead	Single Family Residence
199	235	317 EAST WELBY AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/13/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/13/2024	Non-Lead	Single Family Residence
200	12	2962 S ADAMS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
201	11	2942 S ADAMS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
202	10	2921 S ADAMS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
203	9	2878 S ADAMS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence

204	37	2961 S BLAIR ST	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/06/2024	Non-Lead	Single Family Residence
205	35	2935 S BLAIR ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/06/2024	Non-Lead	Single Family Residence
206	56	320 EAST CAROLE CIR	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/17/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/17/2024	Non-Lead	Single Family Residence
207	55	315 EAST CAROLE CIR	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/06/2024	Non-Lead	Single Family Residence
208	166	2885 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
209	136	354 EAST MAXWELL LN	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
210	137	402 EAST MAXWELL LN	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
211	34	2869 S BLAIR ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
212	33	2853 S BLAIR ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
213	32	2804 S BLAIR ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/30/2024	Non-Lead	Single Family Residence
214	31	2779 S BLAIR ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
215	30	2759 S BLAIR ST	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/3/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/03/2024	Non-Lead	Single Family Residence
216	146	2809 S 300 E	Galvanized	.75 inch M25	Visual inspection at the meter pit	8/29/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/29/2024	Non-Lead	Single Family Residence
217	142	2789 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/28/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residence
218	7	2838 S ADAMS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/28/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residence
219	5	2746 S ADAMS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/28/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residence
220	29	2727 S BLAIR ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
221	340	321 EAST 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/30/2024	Non-Lead	Single Family Residence
222	341	340 EAST 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/30/2024	Non-Lead	Single Family Residence
223	343	366 EAST 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/30/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/30/2024	Non-Lead	Single Family Residence
224	344	403 EAST 2700 S	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	8/30/2024	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	08/30/2024	Non-Lead	Single Family Residence
225	247	2660 S 400 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Unknown - Material Unknown	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Multiple Family Residence
226	342	2664-2694 S 360 E	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	9/12/2024	Unknown - Material Unknown	1.00 inch M70	Visual inspection at the meter pit	09/12/2024	Non-Lead	Single Family Residence
227	128	2617 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
228	117	337 EAST LESLIE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence
229	118	385 EAST LESLIE AVE	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	8/27/2024	Non-Lead - Plastic	Recordall 5/8	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residence

230	226	318 EAST VIDAS AVE	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residenc
231	280	343 EAST VIDAS AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/27/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/27/2024	Non-Lead	Single Family Residenc
232	279	367 EAST VIDAS AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/12/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/12/2024	Non-Lead	Single Family Residenc
233	241	2550 S 400 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/12/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/12/2024	Non-Lead	Single Family Residenc
234	27	385 EAST BERYL AVE	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	9/12/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/12/2024	Non-Lead	Single Family Residenc
235	26	345 EAST BERYL AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
236	25	304 E BERYL AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
237	141	382 EAST OAKLAND AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
238	140	350 EAST OAKLAND AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
239	139	321 EAST OAKLAND AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
240	138	305 E OAKLAND AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Unknown - Material Unknown	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
241	151	350 EAST ROBERT AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
242	152	376 EAST ROBERT AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/23/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
243	195	325 EAST SUNSET AVE	Galvanized	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residenc
244	153	402 EAST ROBERT AVE	Non-Lead - Copper	1 inch M70	Visual inspection at the meter pit	8/23/2024	Non-Lead - Copper	1 inch M70	Visual inspection at the meter pit	08/23/2024	Non-Lead	Single Family Residenc
245	154	460 EAST ROBERT AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residenc
246	231	458 EAST WARNOCK AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residenc
247	229	414 EAST WARNOCK AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residenc
248	227	434 EAST VIDAS AVE	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	8/28/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residenc
249	3	2591 S ADAMS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/13/2024	Unknown - Material Unknown	.75 inch M25	Visual inspection at the meter pit	09/13/2024	Non-Lead	Single Family Residenc
250	119	424 EAST LESLIE AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/22/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residenc
251	287	2645 S MASONIC CIR	Non-Lead - Plastic	1.00 inch M70	Visual inspection at the meter pit	8/22/2024	Non-Lead - Plastic	1.00 inch M70	Visual inspection at the meter pit	08/22/2024	Non-Lead	Single Family Residenc
252	345	459 EAST 2700 S	Unknown - Material Unknown	2 inch T200	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	2 inch T200	Visual inspection at the meter pit	09/06/2024	Non-Lead	Single Family Residenc
253	346	494 EAST 2700 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/06/2024	Non-Lead	Single Family Residenc
254	4	2709 S ADAMS ST	Non-Lead - Copper	Recordall 1	Visual inspection at the meter pit	8/28/2024	Galvanized	Recordall 1	Visual inspection at the meter pit	08/28/2024	Non-Lead	Single Family Residenc
255	275	2774 S 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/21/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residenc

256	6	2811 S ADAMS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residenc
257	281	2826 S 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residenc
258	196	465 EAST SUNSET AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/21/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residenc
259	282	2861 S 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residenc
260	285	2905 S 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/21/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/21/2024	Non-Lead	Single Family Residenc
261	286	2915 S 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
262	268	2953 S 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/12/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/12/2024	Non-Lead	Single Family Residenc
263	270	557 EAST GARDEN AVE	Non-Lead - Copper	1 inch M70	Visual inspection at the meter pit	9/4/2024	Non-Lead - Plastic	1 inch M70	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
264	271	589 EAST GARDEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
265	273	659 EAST GARDEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
266	321	2910 S 700 E (2916 S 700 E)*	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
267	274	680 EAST GARDEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
268	272	620 EAST GARDEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
269	269	2964 S 600 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
270	301	2991 S 600 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
271	290	3019 S 500 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/4/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
272	317	3087 SOUTH 500 E	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/4/2024	Non-Lead - Plastic	Recordall 5/8	Visual inspection at the meter pit	09/04/2024	Non-Lead	Single Family Residenc
273	359	3101 S 500 E	Non-Lead - Copper	.75 M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Copper	.75 M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Single Family Residenc
274	316	3134 SOUTH 700 E		1 INCH M70	Visual inspection at the meter pit			1 INCH M70	Visual inspection at the meter pit		Non-Lead	
275	300	3255 SOUTH 500 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Single Family Residenc
276	298	3220 SOUTH 540 E	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Plastic	.75 INCH M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Single Family Residenc
277	297	3219 SOUTH 540 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Single Family Residenc
278	329	44 WEST 2400 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
279	54	64 WEST BURTON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Building
280	248	2278 S WEST TEMPLE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/13/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/13/2024	Non-Lead	Single Family Residenc
280 A		2262 S. W. Temple St	Non-Lead - Copper		Visual inspection at the meter pit	9/5/2024	Non-Lead - Copper		Visual inspection at the meter pit	09/05/2024	Non-Lead	Single Family Residenc

281	246	2194 S WEST TEMPLE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Building
282	63	161 W COMMONWEALTH AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Building
283	147	2171 S RICHARDS ST	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
284	320	133 E 2400 S	Non-Lead - Copper	.754 inch M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Copper	.754 inch M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Single Family Residenc
285	322	177 E 2400 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/10/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
286	323	225 E 2400 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/5/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/05/2024	Non-Lead	Single Family Residenc
287	324	265 E 2400 S	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/13/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	09/13/2024	Non-Lead	Single Family Residenc
288	105	2389 S 300 E	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	09/06/2024	Non-Lead	Single Family Residenc
289	325	333 EAST 2400 S	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/13/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	09/13/2024	Non-Lead	Single Family Residenc
290	326	381 EAST 2400 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/06/2024	Non-Lead	Single Family Residenc
291	327	413 EAST 2400 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/13/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/13/2024	Non-Lead	Single Family Residenc
292	328	465 EAST 2400 S	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/12/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/12/2024	Non-Lead	Single Family Residenc
293	53	459 EAST BURTON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/16/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/16/2024	Non-Lead	Single Family Residenc
294	51	410 EAST BURTON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/06/2024	Non-Lead	Single Family Residenc
295	50	385 EAST BURTON AVE	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residenc
296	49	354 EAST BURTON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
297	48	322 EAST BURTON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/12/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/12/2024	Non-Lead	Single Family Residenc
298	47	292 E BURTON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
299	46	260 E BURTON AVE	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/13/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	09/13/2024	Non-Lead	Single Family Residenc
300	45	221 E BURTON AVE	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
301	43	176 E BURTON AVE	Non-Lead - Copper	.75 M25	Visual inspection at the meter pit	9/10/2024	Galvanized	.75 M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
302	42	163 E BURTON AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/16/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	09/16/2024	Non-Lead	Single Family Residenc
303	41	136 E BURTON AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	9/10/2024	Galvanized	.75 INCH M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
304	199	124 E TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
305	200	147 E TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/10/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
306	201	176 E TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc

307	202	201 E TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/16/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/16/2024	Non-Lead	Single Family Residenc
308	203	255 E TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/11/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residenc
309	267	2336 S 300 E	Non-Lead - Copper	Recordall 1.5	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	Recordall 1.5	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residenc
310	204	321 EAST TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/11/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/11/2024	Non-Lead	Single Family Residenc
311	205	353 EAST TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/10/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
312	206	396 East Truman Ave	Galvanized	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/9/2024	Non-Lead - Plastic	Recordall 5/8	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
313	230	2339 S 400 E	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/18/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	09/18/2024	Non-Lead	Single Family Residenc
314	210	421 EAST TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
315	211	452 EAST TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/10/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
316	212	484 EAST TRUMAN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
317	265	2316 S 500 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/10/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
318	104	485 EAST HAVEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
319	103	462 EAST HAVEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/10/2024	Non-Lead - Plastic	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
320	102	422 EAST HAVEN AVE	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	09/09/2024	Non-Lead	Single Family Residenc
321	100	394 EAST HAVEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
322	101	355 EAST HAVEN AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
323	95	2305 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
324	94	2281 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
325	240	140 E WENTWORTH AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
326	266	169 E WENTWORTH AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/6/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
327	242	206 E WENTWORTH AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/6/2024	Galvanized	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
328	243	227 E WENTWORTH AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
329	244	260 E WENTWORTH AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
330	245	277 E WENTWORTH AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
331	81	2199 S 300 E	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	1.00 inch M70	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
332	74	2179 S 300 E	Non-Lead - Copper	Recordall 5/8 x 3/4	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	Recordall 5/8	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc



359	313	161 E COMMONWEALTH AVE	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	9/9/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	09/10/2024	Non-Lead	Single Family Residenc
360	165	37 WEST SHELLEY AVE	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	8/13/2024	Non-Lead - Copper	.75 INCH M25	Visual inspection at the meter pit	08/13/2024	Non-Lead	Single Family Residenc
361	253	3106 SOUTH WEST TEMPLE	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	8/13/2024	Non-Lead - Copper	1 INCH M70	Visual inspection at the meter pit	08/13/2024	Non-Lead	Multiple Family Reside
362	84	2956 S GARDEN CIR	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/13/2024	Non-Lead	Single Family Residenc
363	122	2556 S 300 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Unknown - Material Unknown	.75 inch M25	Visual inspection at the meter pit	08/13/2024	Non-Lead	Single Family Residenc
364	228	2315 S 400 E	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	8/13/2024	Non-Lead - Copper	.75 inch M25	Visual inspection at the meter pit	08/13/2024	Non-Lead	Single Family Residenc